



Technical Service Bulletin

Cobra Motorcycle Mfg.


11511 Springfield Road
North Lima, Ohio 44452

(330) 549-9600 phone
(330) 549-9605 fax

TSB1004: 2004 King & CM 50 engine case screws

April 2, 2004

During new product break-in check the tightness of the engine case screws.



Proper torque is 80 in-lb (9 Nm).

If these screws become loose the machine could experience an air leak and/or an oil leak.