



# Technical Service Bulletin

**Cobra Motorcycle Mfg.**

11511 Springfield Road  
North Lima, Ohio 44452

(330) 549-9600 phone  
(330) 549-9605 fax

## TSB0604: 2004 spark plug for King, CM 50 & PW3.

April 2, 2004

The extended tip Champion spark plug that comes stock in the 2004 King 50, CM50, and PW3 protrude further into the combustion chamber than past year's spark plugs, and are not compatible with prior years models cylinder heads. Do not attempt to install this spark plug in any model except a 2004 King 50 engine.