



Technical Service Bulletin

Cobra Motorcycle Mfg.

11511 Springfield Road
North Lima, Ohio 44452

(330) 549-9600 phone
(330) 549-9605 fax

TSB0704: King front brake caliper bracket

April 2, 2004

The old aluminum front disc brake caliper bracket has been discontinued and replaced with a stronger steel unit, BCKG0008.