



# Technical Service Bulletin

**Cobra Motorcycle Mfg.**

11511 Springfield Road  
North Lima, Ohio 44452

(330) 549-9600 phone  
(330) 549-9605 fax

## TSB1504: 2004 CM & PW shock spring

April 8, 2004

There is an error in the 2004 CM & PW with respect to the color of the optional shock springs.

The manual should show

Weight of Rider (lb)	Fork Spring	Shock Spring
Less than 38 (light)	KCMZ0012A	SCMUOH04 (275 lb/in) <b>red</b>
38 – 45 (std)	KCMZ0012	SCMUOH05 (285 lb/in) yellow
46 to 55 (stiff)	KCMZ0012B	SCMUOH06 (295 lb/in) <b>white</b>