



# Technical Service Bulletin

**Cobra Motorcycle Mfg.**


11511 Springfield Road  
North Lima, Ohio 44452

(330) 549-9600 phone  
(330) 549-9605 fax

## TSB0804: 2004 King rear brake caliper carrier pad

April 2, 2004

An adhesive backed rubber pad that acts as a cushion under the rear brake caliper carrier was absent from certain 2004 King models. The pads are available from Cobra and should be applied to the bottom surface of the brake carrier that mates against the top of the swingarm.



Apply rubber pad to the carrier in this area